

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/25/2023

Submitted Date:

04/25/2023

Document Number:

707601150

**FIELD INSPECTION FORM**

Loc ID 306456 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288952	WELL	SI	08/01/2015	GW	123-24697	ROUSE-USX A 5-19	SI

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Shut-In | SI.  
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025).  
(Well(s): 3: Temporarily Abandoned | TA ; 2: Shut-In | SI).

Refer to Field Inspection Report doc. #707601144 and/or Location ID #302563 for Battery / Facility, Equipment info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.519192,-104.582283
Comment:	Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025). (Well(s): 3: Temporarily Abandoned   TA ; 2: Shut-In   SI).				
Corrective Action:					Date:

**Paint**

Condition:

Other (Content):

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input style="width:100px;" type="text"/>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width:100px;" type="text"/>

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: <input style="width:100px;" type="text"/>

**Inspected Facilities**

Facility ID: 288952 Type: WELL API Number: 123-24697 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.  
Locked-Out, Tagged-Out | LOTO.  
Yellow LTSI tag posted at well.  
COGCC records last prod: 07/2015.  
SI/TA well per variance doc. #401474555. (NOBLE).  
  
Form 6A on file. Out-of-Svc Designation.  
Date: 07/01/2015. Approved.

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/09/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 04/25/2023 at approximately 11:43 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: ROUSE-USX A-66N64W/5NWNW                      Location ID: 306456                      Well Name(s):                      Rouse-USX A 5-19.                      API:                      123-24697.                      Location County: Weld County, Colorado                      Weather: Overcast, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Shut-In   SI.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025).                      (Well(s): 3: Temporarily Abandoned   TA ; 2: Shut-In   SI).</p> <p>Refer to Field Inspection Report doc. #707601144 and/or Location ID #302563 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/25/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601151	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093453">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6093453</a>