

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 1 – 35-2H Wellhead

Photo 2 – 26-2H Wellhead

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 3 – Stained Soil



Photo 4 – Stained Soil

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 5 – Stained Soil



Photo 6 – Stained Soil

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 7 – Separator and Heater Treater



Photo 8 – Tank Battery Sign

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 9 – Tank Battery



Photo 10 – Tank Labels

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275




Photo 11 – Tank Labels



Photo 12 – Sales Gas Meter

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 13 – VRU



Photo 14 – ECDs

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 15 – Stained Soil at Separator



Photo 16 – Heater Treater

Inspection Photos
Location Name: Crow Valley 7-62-35-2H
Location ID: 427275



Photo 17 – Unmarked Riser at Gas Meters