


**Inspection Photos**  
**Location Name: Crow Valley 7-62-34-2H**  
**Location ID: 428002**



**Photo 1 – Tank Battery**



**Photo 2 – Water Tank Labels**

**Inspection Photos**  
**Location Name: Crow Valley 7-62-34-2H**  
**Location ID: 428002**



**Photo 3 – Tank Battery Sign**



**Photo 4 – Heater Treaters**



**Inspection Photos**  
**Location Name: Crow Valley 7-62-34-2H**  
**Location ID: 428002**



**Photo 5 – ECD**



**Photo 6 – Sales Gas Meter and VRU**

**Inspection Photos**  
**Location Name: Crow Valley 7-62-34-2H**  
**Location ID: 428002**



**Photo 7 – Pumping Unit**



**Photo 8 – 34-2H**



**Inspection Photos**  
**Location Name: Crow Valley 7-62-34-2H**  
**Location ID: 428002**



**Photo 9 – Plunger Lubricator Cap**



**Photo 10 – Unused Rods**

**Inspection Photos**  
**Location Name: Crow Valley 7-62-35-2H**  
**Location ID: 427275**



**Photo 11 – Chemical Labels missing**