

Inspection Photos
Location Name: Crow Valley 7-62-22-2H
Location ID: 428324



Photo 1 – Tank Battery



Photo 2 – Stained Soil

Inspection Photos
Location Name: Crow Valley 7-62-22-2H
Location ID: 428324



Photo 3 – Pumping Unit



Photo 4 – Propane

Inspection Photos
Location Name: Crow Valley 7-62-22-2H
Location ID: 428324



Photo 5 – ECD



Photo 6 – Gas Meter

Inspection Photos
Location Name: Crow Valley 7-62-22-2H
Location ID: 428324



Photo 7 – Heater Treater



Photo 8 – Tank Battery

Inspection Photos

Location Name: Crow Valley 7-62-22-2H

Location ID: 428324



Photo 9 – Tank Battery Sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources