

# Inspection Photos

Loc: 333537

Operator: SIMCOE LLC / LOGOS OPERATING LLC

Inspection Date: 4/18/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Loc: 333537 | Date: 4/18/2023

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There is vehicle rutting and tracking along the road that needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 4/18/2023



## Inspection Photos



**Photo 1.** Facing northwest along the access road. There is vehicle rutting and tracking along the road that needs to be repaired and stabilized. Gate was locked and couldn't go any further.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 4/18/2023