

Inspection Photos

4/24/2023

Operator: SCOUT ENERGY MANAGEMENT LLC

- 10779

103-07604

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779
103-07604



Photo 1: Photos 1-2 provide an overview of the well pad from east, southeast, southwest to west. Road around well remains apparent. Gravel, compaction issues remaining.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779
103-07604



Photo 1: See comments under photo 1.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779
103-07604



Photo 3: Gravel/road base remaining on Location.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779
103-07604



Photo 4: Photos show concrete debris, and pipe observed on both the southern, and northern ends of the Location.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779
103-07604



Photo 5: Pipe debris remaining on Location.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779
103-07604



Photo 6: Reclamation inadequate along access road.

Inspection Photos

Operator Name: SCOUT ENERGY MANAGEMENT LLC - 10779
103-07604



Photo 7: Undesirable Plant Species (Halogeton) from the 2022 growing season, and this years germination.