

**Inspection Photos**  
**Location Name: Carter 21-33**  
**Location ID: 329511**



**Photo 1 WH sign .**



**Photo 2 WH.**

**Inspection Photos**  
**Location Name: Carter 21-33**  
**Location ID: 329511**



**Photo 3 Pump Jack.**



**Photo 4 electric panel**



**Inspection Photos**  
**Location Name: Carter 21-33**  
**Location ID: 329511**



**Photo 5 TB sign.**

**Photo 6 TB.**



**Inspection Photos**  
**Location Name: Carter 21-33**  
**Location ID: 329511**



**Photo 7 HHS.**

**Photo 8 Gas Meter Run.**





**Inspection Photos**  
**Location Name: Carter 21-33**  
**Location ID: 329511**



**Photo 9 Flow line manifold.**

**Photo 10 Stained soil by the NE crude tank, pin hole leak.**