

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 33-20 Pad

Location ID: 335136



Photo # 6217 From entrance to location



Photo # 6218 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 33-20 Pad

Location ID: 335136



Photo # 6227 Stained soils & gravel



Photo # 6225 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 33-20 Pad

Location ID: 335136



Photo # 6230 Debris




Photo # 6231 Debris