

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 19 Pad
Location ID: 322456



Photo # 6410 From entrance to location



Photo # 6411 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 19 Pad
Location ID: 322456



Photo # 6412 Location



Photo # 6413 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 19 Pad

Location ID: 322456



Photo # 6418 Chemical containment is approximately 3/4 full/Failure to maintain chemical BMP

Photo # 6253 From Inspection 708900345 conducted on 04/25/2023