

Inspection Photos

Location Name: ROUSE USX AB-67N64W/33SWSW

Location #: 302629




Photo #1

Rouse USX AB 33-13 (123-29500) Wellsite

Shut-In | SI



Photo #2

**Rouse USX AB 33-13, 33-11, 33-14, 33-25,
Rouse USX A 05-01, 05-02, 05-07, 05-08, 5-17**

Battery site

Inactive | Shut-down

Inspection Photos

Location Name: ROUSE USX AB-67N64W/33SWSW

Location #: 302629



Photo #3

**Rouse USX AB 33-13, 33-11, 33-14, 33-25,
Rouse USX A 05-01, 05-02, 05-07, 05-08, 5-17**

Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #4

**Rouse USX AB 33-13, 33-11, 33-14, 33-25,
Rouse USX A 05-01, 05-02, 05-07, 05-08, 5-17**

Battery site

Inactive | Shut-down

Separator(s), ECD(s)

Inspection Photos

Location Name: ROUSE USX AB-67N64W/33SWSW

Location #: 302629




Photo #5

**Rouse USX AB 33-13, 33-11, 33-14, 33-25,
Rouse USX A 05-01, 05-02, 05-07, 05-08, 5-17**

Battery site

Inactive | Shut-down

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources