

Inspection Photos

Loc: 322112

Operator: FOUR CORNERS ENERGY LLC

Inspection Date: 4/19/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322112 | Date: 4/19/2023

Inspection Photos



Photo 1. Center of the location facing east. Perennial vegetation has established and the area surround this site is cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322112 | Date: 4/19/2023

Inspection Photos




Photo 2. Center of the location facing north. Perennial vegetation has established and the area surround this site is cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322112 | Date: 4/19/2023

Inspection Photos



Photo 3. Center of the location facing west. Perennial vegetation has established and the area surround this site is cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322112 | Date: 4/19/2023

Inspection Photos



Photo 4. Center of the location facing south. Perennial vegetation has established and the area surround this site is cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc:322112 | Date: 4/19/2023