

Inspection Photos
Location Name: Clementine B. Coburn B1
Location ID: 318481



Photo 1 WH sign old operator sign.

Photo 2 WH.

Inspection Photos
Location Name: Clementine B. Coburn B1
Location ID: 318481



Photo 3 Dead weeds around WH and pump jack.

Photo 4 Dead weeds around the ancillary equipment.

Inspection Photos
Location Name: Clementine B. Coburn B1
Location ID: 318481



Photo 5 TB sign.

Photo 6 TB, dead weeds along base of tank.

Inspection Photos
Location Name: Clementine B. Coburn B1
Location ID: 318481



Photo 7 Dead weeds inside of the TB berm.

Photo 8 dead weeds along around Gas Meter Runs.

Inspection Photos
Location Name: Clementine B. Coburn B1
Location ID: 318481



Photo 9 Dead weeds around the flow line manifold.

Photo 10 Dead weeds around the HHS.