

Inspection Photos
Location Name: John A. Kunzman 2
Location ID: 332891



Photo 1 WH sign.

Photo 2 WH.

Inspection Photos
Location Name: John A. Kunzman 2
Location ID: 332891



Photo 3 Pump Jack.



Photo 4 Dead weeds around the Ancillary Equip.

Inspection Photos
Location Name: John A. Kunzman 2
Location ID: 332891



Photo 5 Oil staining on Concrete pad from leaking PJ gear box .



Photo 6 Oil staining on Concrete pad from leaking PJ gear box .