

# Interim Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317358

Inspection Document #: 708200183

Washington County, CO

NENW Section 12 T3S R50W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Christianson-63S50W  
Location ID: 317358



**Photo 1.** Trash and debris observed on location that will need to be properly disposed of.



**Photo 2.** Wildlife netting absent on secondary containment.

Inspection Photos  
Location Name: Christianson-63S50W  
Location ID: 317358



**Photo 3.** Interim areas do not appear to be progressing towards reclamation standards with unstabilized soils and lack of desirable vegetation.

Inspection Photos  
Location Name: Christianson-63S50W  
Location ID: 317358



**Photo 4.** See comments in Photo 3.