

# Interim Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: SMITH ENERGY LLC -10536

Location ID: 317364

Inspection Document #: 708200182

Washington County, CO

NENW Section 12 T3S R50W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Location ID: 317364**



**Photo 1.** Pipe fencing is in disrepair and requires removal as it is now considered debris. Suggest Operator install new fencing or high visibility marker as the well is situated in cropland.



Inspection Photos  
Location Name: Christianson-Niobrara  
Location ID: 317364



**Photo 2.** See comments in Photo 1.



Inspection Photos  
Location Name: Christianson-Niobrara  
Location ID: 317364



**Photo 3.** Wildlife netting not installed around secondary containment.