

Interim Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 317355

Inspection Document #: 708200189

Washington County, CO

SWNE Section 12 T3S R50W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355



Photo 1. Unused equipment on location.

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355



Photo 2. Stained soil observed on and next to pumpjack foundation will require proper cleanup Per Rule 905.e.

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355




Photo 3. See comments in Photo 2.

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355



Photo 4. No wildlife netting installed on secondary containment.

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355



Photo 5. Interim areas are not progressing towards reclamation standards with large areas of bare soil observed around the location. Additional reclamation activities will need to be performed in order to meet Rule 1003 standards.

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355



4/20/23, 12:26 PM
263° W
COGCC

Photo 6. See comments in Photo 5.

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355



Photo 7. See comments in Photo 5.

Inspection Photos
Location Name: Young*J-63S50W
Location ID: 317355



Photo 8. See comments in Photo 5.