

Interim Reclamation and Stormwater Inspection

Date: 04/20/2023

Operator: SMITH ENERGY LLC - 10536

Location ID: 317352

Inspection Document #: 708200191

Washington County, CO

NWNE Section 12 T3S R50W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Christianson-Niobrara
Location ID: 317352



Photo 1. Desirable vegetation establishment is evident throughout the interim areas and is reflective of reference area vegetation.

Inspection Photos
Location Name: Christianson-Niobrara
Location ID: 317352



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Christianson-Niobrara
Location ID: 317352



Photo 3. Previous inspection (Doc #688312304) noted erosion occurring underneath produced water tank and secondary containment berms. At this time of this inspection, it does not appear the Operators has performed any corrective actions as the location appears to be in the same condition as previous inspection. Severe erosion is occurring and requires maintenance and/or repairs.

Inspection Photos
Location Name: Christianson-Niobrara
Location ID: 317352



Photo 4. NFPA label is not legible and requires replacement.

Inspection Photos
Location Name: Christianson-Niobrara
Location ID: 317352



Photo 5. Unused equipment on location.

Inspection Photos
Location Name: Christianson-Niobrara
Location ID: 317352



Photo 6. See comments in Photo 5.

Inspection Photos
Location Name: Christianson-Niobrara
Location ID: 317352



Photo 7. See comments in Photo 5.