


**Operator: BONANZA CREEK ENERGY OPERATING COMPANY**


**Location Name: Crow Valley V-21 Pad**

**Loc ID: 159489**


**Inspection: 696304818**



**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**



**Exhibit E**



**Exhibit F**



**Exhibit G**



**Exhibit H**



**Exhibit I**

**CA:** Unmarked Risers at Wellhead, VRU and Gas Meter; See photos. Comply with Rule 606.

**CA Resolution:** Risers at Wellhead, VRU and Gas Meter have all been marked as of 4/26/2023 to comply with Rule 606.



**Exhibit A**



**Exhibit B**

**CA:** Stained Soil at Gas Engine; See photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

**CA Resolution:** Oily waste identified at Gas Engine has been properly disposed of to comply with Rule 905.e.



**Exhibit A**



**Exhibit B**

**CA:** Tumbleweeds at Separator; See photos. Comply with Rule 606.

**CA Resolution:** Tumbleweeds and weed debris were removed/mowed on 4/26/2023. The location now complies with Rule 606.