

Inspection Photos

API: 071-06514

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/27/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06514 | Date: 4/27/2023

Inspection Photos



Photo 1. Facing south toward the access road. The erosion along the road and culvert outlet was repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06514 | Date: 4/27/2023

Inspection Photos



Photo 2. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06514 | Date: 4/27/2023

Inspection Photos



Photo 3. Along the main road at Lat/Long:37.14002,-104.68079. There is rock rip/rap that has been hauled into this area for repair of the culvert outlet erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06514 | Date: 4/27/2023