

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2023

Submitted Date:

04/28/2023

Document Number:

707601172

FIELD INSPECTION FORM

Loc ID 427641 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427634	WELL	PA	08/27/2021	OW	123-35058	Ball Ranch GW27-63HN	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.
(AMI: Alternate Method Inspection).
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment removed.
Abandoned Battery SE corner GPS coordinates: 40.627220 / -104.430160

Follow-up to Field Inspection Report doc. #707601036 dated 03/31/2023.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	<p>Prior FIR: Unnecessary equipment (2-gas meter runs, blowdown header) at Abandoned Battery site. Refer to Rule 606.a for guidance. *Remove unnecessary equipment (2-gas meter runs, blowdown header) from Abandoned Battery site. Comply with Rule 606.a. Corrective Action date: 06/05/2023. (60-days). See photo(s) #2, 3.</p> <p>This FIR: ** Unnecessary equipment (2-gas meter runs) at Abandoned Battery site. Removed as of 04/24/2023. Noble Energy advised that gas blowdown header remains in use. See photo(s) #2, 3, 4. (Photo #4: Operator provided). Corrective Action(s), NOW resolved.</p>		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:		corrective date
Type: Gas Meter Run	# 0	
Comment:		
Corrective Action:		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities

Facility ID: 427634 Type: WELL API Number: 123-35058 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 04/28/2023 at approximately 10:45 hrs. I, Bret Evins, conducted an AMI: Alternate Method inspection at: Operator Name: NOBLE ENERGY INC Location Name: Ball Ranch/GW27-63HN Location ID: 427641 Well Name(s): Ball Ranch GW27-63HN. API: 123-35058. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.627220 / -104.430160</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6S on file. Plugging, cut/cap date: 08/27/2021. Approved. Plugged & Abandoned PA well GPS coordinates: 40.628410 / -104.429620</p> <p>Follow-up to Field Inspection Report doc. #707601036 dated 03/31/2023.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Unnecessary equipment (2-gas meter runs, blowdown header) at Abandoned Battery site. Refer to Rule 606.a for guidance. *Remove unnecessary equipment from Abandoned Battery site. Comply with Rule 606.a. Corrective Action date: 06/05/2023. (60-days). See photo(s) #2, 3. ** Unnecessary equipment (2-gas meter runs) at Abandoned Battery site. Removed as of 04/24/2023. Noble Energy advised that gas blowdown header remains in use. See photo(s) #2, 3, 4. (Photo #4: Operator provided). Corrective Action(s), NOW resolved.</p> <p>Field Inspection Report Resolution FIRR doc. #403383831 indicates Unnecessary Equipment: Gas meter runs have been removed as of 04/24/2023. Operator provided photo for verification. Corrective Action(s) have been resolved.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601173	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6097510