

Inspection Photos

Location Name: WEST IRRIGATION USX AB/33-23

Location #: 421229



Photo #1

West Irrigation USX AB 33-23 (123-32865) Wellsite
Temporarily Abandoned | TA



Photo #2

West Irrigation USX AB 33-15, 33-23 Battery site
Inactive | Shut-down
Equipment documented: Loc. # 306369
Formerly served West Irrigation-USX AB 33-10;
Plugged & Abandoned | PA