

# TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/17NENW

## Location # 324441



Location – Photo #02661



Location – Photo #02669

# TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/17NENW

Location # 324441



Wellhead – Photo #02668



Separator/Gas Meter – Photo #02663

# TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/17NENW

Location # 324441



Tank Battery – Photo #02664



Location Lacks Stabilization – Photo #02670

# TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/17NENW

Location # 324441



Location Lacks Stabilization – Photo #02671



Insufficient Vehicle Tracking BMPs – Photo #02672

# TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/17NENW

Location # 324441



**Lease Road Degradation/Transportation of Sediment – Photo #02688**

**Lease Road Degradation/Transportation of Sediment– Photo #02690**