

TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/8NWNE

Location # 324442



Location – Photo #02674



Wellhead – Photo #02681

TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/8NWNE

Location # 324442



Separator/Gas Meter – Photo #02683



Tank Battery – Photo #02675

TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/8NWNE

Location # 324442



Storage of Unused Equipment – Photo #02678



Location Lacks Stabilization – Photo #02684

TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/8NWNE

Location # 324442



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #02686



Lease Road Degradation/Transport of Sediment – Photo #02688

TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/8NWNE

Location # 324442



**Lease Road Degradation/Transport of Sediment –
Photo #02690**