

Inspection Photos
Location Name: Merlin Pad
Location ID: 456260



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Merlin Pad
Location ID: 456260



Photo 3: Unused equipment



Photo 4: Unused equipment

Inspection Photos
Location Name: Merlin Pad
Location ID: 456260



Photo 5: No grounding



Photo 6: Trash