

Inspection Photos  
Location Name: Raindance FD Pad  
Location ID: 427917





Photo 1: Tank Battery Sign



Photo 2: No NFPA placard

**Inspection Photos**  
**Location Name: Raindance FD Pad**  
**Location ID: 427917**



**Photo 3: Trash**



**Photo 4: Equipment storage**