

Inspection Photos

Location Name: HSR-Gardner-64N65W 31NENW

Location ID: 327801



Photo #1 Well



Inspection Photos
Location Name: HSR-Gardner-64N65W 31NENW
Location ID: 327801



Photo #2 mechanical condition & Oily Waste



Photo #3 Oily Waste



Inspection Photos
Location Name: HSR-Gardner-64N65W 31NENW
Location ID: 327801



Photo #4 Oily Waste




Photo #5 Removed Kimray valve

