

Inspection Photos

API: 071-09106

Operator: OGRIS OPERATING LLC

Inspection Date: 5/1/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09106 | Date: 5/1/2023

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09106 | Date: 5/1/2023

Inspection Photos



Photo 2. Facing toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09106 | Date: 5/1/2023

Inspection Photos



Photo 3. The fence around the lined pit is in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09106 | Date: 5/1/2023