

Inspection Photos

API: 071-08656

Operator: OGRIS OPERATING LLC

Inspection Date: 5/1/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08656 | Date: 5/1/2023

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08656 | Date: 5/1/2023

Inspection Photos



Photo 2. There is no freeboard marker in the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08656 | Date: 5/1/2023

Inspection Photos



Photo 3. Facing toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08656 | Date: 5/1/2023

Inspection Photos



Photo 4. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08656 | Date: 5/1/2023

Inspection Photos



Photo 5. There is oily fluid in the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08656 | Date: 5/1/2023