

# Inspection Photos

API: 071-09631

Operator: OGRIS OPERATING LLC

Inspection Date: 5/1/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09631 | Date: 5/1/2023

## Inspection Photos



**Photo 1.** Facing east along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09631 | Date: 5/1/2023

## Inspection Photos



**Photo 2.** Facing east toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09631 | Date: 5/1/2023

## Inspection Photos



**Photo 3.** Facing toward the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09631 | Date: 5/1/2023

## Inspection Photos



**Photo 4.** The fence is maintained around the pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09631 | Date: 5/1/2023

## Inspection Photos



**Photo 5.** There is oily fluid in the engine skid that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09631 | Date: 5/1/2023