

Inspection Photos

Location: Fundare Resources Operating Company LLC / Wildhorse 16-13H

Facility ID: 451870



COLORADO


Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location: Fundare Resources Operating Company LLC / Wildhorse 16-13H

Facility ID: 451870



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location: Fundare Resources Operating Company LLC / Wildhorse 16-13H

Facility ID: 451870



Inspection Photos

Location: Fundare Resources Operating Company LLC / Wildhorse 16-13H

Facility ID: 451870



Inspection Photos

Location: Fundare Resources Operating Company LLC / Wildhorse 16-13H

Facility ID: 451870



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location: Fundare Resources Operating Company LLC / Wildhorse 16-13H

Facility ID: 451870



Inspection Photos

Location: Fundare Resources Operating Company LLC / Wildhorse 16-13H

Facility ID: 451870



Latitude: 40.748450
Longitude: -103.989998
Elevation: 1520.72±6.00 m
Accuracy: 5.13 m
Time: 04-11-2023 13:43:46
Note: Inadequate wildlife protection

Photo taken by: CAS



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources