


Caerus Piceance LLC
Freedom Unit-62S97W 16SWNW
Location #336042



Location signage



Access road into location



**Caerus Piceance LLC
Freedom Unit-62S97W 16SWNW
Location #336042**



Entrance to location



Containments full of liquid. Lack of freeboard.



Caerus Piceance LLC
Freedom Unit-62S97W 16SWNW
Location #336042



No wildlife protection on pop off risers



No wildlife protection on pop off risers

**Caerus Piceance LLC
Freedom Unit-62S97W 16SWNW
Location #336042**



Vehicle tracking during wet conditions



Wet conditions vehicle tracking exiting location

**Caerus Piceance LLC
Freedom Unit-62S97W 16SWNW
Location #336042**



View from Northwest corner of location



View from Southwest corner of location

**Caerus Piceance LLC
Freedom Unit-62S97W 16SWNW
Location #336042**



View from Southeast corner of location



View from Northeast corner of location