

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403390612

Date Received:

05/01/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10409

Name of Operator: PEAKVIEW OPERATING COMPANY LLC

Address: 2427 WEST KETTLE CIRCLE

City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Wise, Wayne

(405) 826-7013

wwise@peakviewenergy.com

Walters, Steve

720-402-3081

swalters@peakviewenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 707800247

Inspection Date: 03/29/2023

FIR Submit Date: 03/31/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC

Company Number: 10409

Address: 2427 WEST KETTLE CIRCLE

City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 312916

Location Name: VOLOSHIN-MORTON-66N90W

Number: 8NESE

County: \_\_\_\_\_

Qtrqr: NESE Sec: 8 Twp: 6N Range: 90W Meridian: 6

Latitude: 40.491569 Longitude: -107.509158

FACILITY - API Number: 05-081-

-00

Facility ID: 312916

Facility Name: VOLOSHIN-MORTON-66N90W

Number: 8NESE

Qtrqr: NESE Sec: 8 Twp: 6N Range: 90W Meridian: 6

Latitude: 40.491569 Longitude: -107.509158

CORRECTIVE ACTIONS:

1 CA# 168824

Corrective Action: Install or repair required BMPs

Date: 05/05/2023

Response: CA COMPLETED

Date of Completion: 04/26/2023

Operator Comment: Stock piled road base material located at the NW corner of the location, was removed Wednesday April 26, 2023. In the fall of 2022, new containment waddles were placed around the top soil mound.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: One of the attached photos shows that the road base material has been removed, and the other photo shows the straw waddles encompassing the top soil mound.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: \_\_\_\_\_

Title: Operations Engineer

Date: 5/1/2023 9:18:55 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403390622	Road Base Removal
403390624	Top Soil Containment

Total Attach: 2 Files