

Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Location Name: Crow Valley 7-62-35 2H

Loc ID: 427275

Inspection: 696304820



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Stained Soil at Heater Treater; See photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

CA Resolution: Stained soil / oily waste at identified area has been properly addressed and cleared to comply with Rule 905.e.



Exhibit A



Exhibit B

CA: Produced Water Tanks - Content and NFPA Labels; See photos. Install sign to comply with Rule 605.h.

CA Resolution: New content and NFPA labels were installed on water tanks to comply with Rule 605.h