

# Final Reclamation Inspection

April 27, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 322607

Inspection Document #: 697504636

Weld County, CO

SENW Section 13 T6N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: R. ANDERSON UNIT #1-13  
Location ID: 322607



**Photo 1.** Photo taken from the well location, facing East. Photo illustrates the surface owner has reseeded the entire corner portion.



**Photo 2.** Photo taken from the well location, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: R. ANDERSON UNIT #1-13  
Location ID: 322607



**Photo 3.** Photo taken from the well location, facing West. See comments under Photo 1.




**Photo 4.** Photo taken from the well location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: R. ANDERSON UNIT #1-13  
Location ID: 322607



**Photo 5.** Reference photo taken from the well location, facing West. See comments under Photo 1.



**Photo 6.** Aerial imagery of the well location and the entire corner portion that was reseeded by the surface owner.