

Final Reclamation Inspection

April 27, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 322935

Inspection Document #: 697504641

Weld County, CO

SWNE Section 12 T6N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DEWALT-66N65W/12SWNE
Location ID: 322935



Photo 1. COGCC GISOnline aerial imagery from 2015 illustrates active operation, illustrating the tank battery, access road, and well location.

Inspection Photos
Location Name: DEWALT-66N65W/12SWNE
Location ID: 322935




Photo 2. COGCC GISOnline aerial imagery from 2021 illustrates after plugging and abandonment operations.

Inspection Photos

Location Name: DEWALT-66N65W/12SWNE

Location ID: 322935



Photo 3. Photo taken from the associated offsite tank battery, facing North. Photo illustrates the Operator has performed final reclamation at the tank battery and has met Rule 1004 standards.



Photo 4. Photo taken from the associated offsite tank battery, facing East. See comments under Photo 3.

Inspection Photos

Location Name: DEWALT-66N65W/12SWNE

Location ID: 322935



Photo 5. Photo taken from the associated offsite tank battery, facing Southeast. See comments under Photo 3.



Photo 6. Photo taken from the associated offsite tank battery, facing South. See comments under Photo 3.

Note- surface owner appears to be using portions of the well location access road for agricultural purposes.