

Interim Reclamation and Stormwater Inspection

April 27, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 429310

Inspection Document #: 697504648

Weld County, CO

NWNE Section 12 T6N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources_S

Inspection Photos
Location Name: Holton 31-12
Location ID: 429310



Photo 1. Google Earth aerial imagery from 10/14/2017 illustrates when the Operator drilled additional wells (orange circle) at the location. The first well was spud in 2012 (red circle;123-35776).

Inspection Photos
Location Name: Holton 31-12
Location ID: 429310



Photo 2. Google Earth aerial imagery from 9/12/2018 illustrates the Operator performed interim reclamation activities to reduce all area not needed for production operations.

Inspection Photos
Location Name: Holton 31-12
Location ID: 429310



Photo 3. Google Earth aerial imagery from 6/11/2021 illustrates the Operator has plugged the original well (123-35776) but has failed to further reduce all areas not needed for production operations. Operator should have performed interim reclamation by no later than 10/10/2020. The southern/southeastern well pad can be further reclaimed per Rule 1003.

Inspection Photos
Location Name: Holton 31-12
Location ID: 429310



Photo 4. Photo taken from the western well pad, facing East. See comments under Photo 3.



Photo 5. Photo taken from the western well pad, facing Southeast. See comments under Photo 3.