

Final Reclamation Inspection

April 27, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 305432

Inspection Document #: 697504656

Weld County, CO

SWNW Section 3 T6N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CORNISH #12-3
Location ID: 305432




Photo 1. COGCC GISOnline 2021 aerial imagery illustrates the section of gravel left in place.

Photo also illustrates where approximate photo locations were taken from.

Inspection Photos
Location Name: CORNISH #12-3
Location ID: 305432



Photo 2. Photo taken from the southern well location access road, facing North. Photo illustrates gravel has not been removed as illustrated in the previous photo.



Photo 3. Photo taken along a portion of the well location access road, facing East. Photo illustrates the access road is mostly bare ground and weedy, annual vegetation.

Inspection Photos
Location Name: CORNISH #12-3
Location ID: 305432



Photo 4. Close up photo illustrates Kochia establishment and little to no germination of desirable plant species.



Photo 5. Photo taken along a portion of the well location access road, facing East. See comments under Photo 3.

Inspection Photos
Location Name: CORNISH #12-3
Location ID: 305432



Photo 6. Photo taken from the well location, facing East. See comments under Photo 3.



Photo 7. Photo taken along a portion of the well location access road, facing North. See comments under Photo 3.

Inspection Photos
Location Name: CORNISH #12-3
Location ID: 305432



Photo 8. Reference photo taken along a portion of the well location access road, facing East. Photo illustrates the reference vegetation in the foreground with a portion of the well location access road in the background.