

Final Reclamation Inspection

April 27, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 332492

Inspection Document #: 697504659

Weld County, CO

NWNW Section 3 T6N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CORNISH #11-3
Location ID: 332492



Photo 1. Photo taken from the western well location access road, facing East. Photo illustrates the access road is mostly bare ground and weedy, annual vegetation.



Photo 2. Photo taken along a portion of the well location access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: CORNISH #11-3
Location ID: 332492



Photo 3. Photo taken from the well location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: CORNISH #11-3
Location ID: 332492



Photo 5. Photo taken from the western associated offsite tank battery, facing East. Photo illustrates bare patches, weedy vegetation with some establishment of desirable species (Crested wheatgrass).



Photo 6. Photo taken from the central associated offsite tank battery, facing East. See comments under Photo 5.

Inspection Photos
Location Name: CORNISH #11-3
Location ID: 332492



Photo 7. Reference photo taken east of the well location, facing East.