

Interim Reclamation and Stormwater Inspection

April 27, 2023

Operator: NOBLE ENERGY INC - #100322

Location ID: 302349

Inspection Document #: 697504661

Weld County, CO

NWNE Section 3 T6N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BUCKCHERRY USX AA #03-02
Location ID: 302349



Photo 1. Photo taken from the associated offsite tank battery, facing West. Photo illustrates the division of the shared tank battery with PDC. PDC is to the right of the weedy fence line and Noble is to the left of the weedy fence line.



Photo 2. Photo taken from within the Noble tank battery, facing West. Photo illustrates weedy, annual vegetation that is not reflective of reference areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504661

Inspection Photos
Location Name: BUCKCHERRY USX AA #03-02
Location ID: 302349



Photo 3. Photo taken from within the Noble tank battery, facing West. See comments under Photo 2.



Photo 4. Reference photo taken north of the tank battery, facing East.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504661

Inspection Photos
Location Name: BUCKCHERRY USX AA #03-02
Location ID: 302349



Photo 5. Google Earth aerial imagery from 9/25/2018 illustrates the shared tank battery. PDC's portion of the tank battery is the northern half, while Noble's portion is the southern half.



Photo 6. Google Earth aerial imagery from 2/2020 illustrates PDC's active portion, while Noble's portion has been fenced off.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697504661