

Inspection Photos
Location Name: Koshio #1
Location ID: 332953



Photo 1 WH sign.

Photo 2 WH.

Inspection Photos
Location Name: Koshio #1
Location ID: 332953



Photo 3 Pump Jack.

Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Koshio #1
Location ID: 332953



Photo 5 Tank battery sign.

Photo 6 Tank battery.

Inspection Photos
Location Name: Koshio #1
Location ID: 332953



Photo 7 Stained soil by the load out line.

Photo 8 Stained soil by the produced water vessel.

Inspection Photos
Location Name: Koshio #1
Location ID: 332953



Photo 9 Stained soil by the PW vessel.

Photo 10 Vertical Heater Treater.