

**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 1 WH sign old operator sign.**

**Photo 2 WH.**



**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 3 Stained soil around the WH.**

**Photo 4 WH Sign.**



**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 5 WH.**



**Photo 6 Possible leaking WH.**



**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 7 WH sign.**



**Photo 8 WH.**



**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 9 WH sign.**



**Photo 10 WH.**

**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 11 TB signs.**



**Photo 12 TB.**

**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 13 ECDs.**



**Photo 14 Horizontal Heated separators.**

**Inspection Photos**  
**Location Name: SRC Pratt 24-29D**  
**Location ID: 3318975**



**Photo 15 Gas Meter Run, pig station.**



**Photo 16 TO flow lines.**