

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 16 Pad

Location ID: 335484



Photo # 6833 From entrance to location



Photo # 6834 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 16 Pad

Location ID: 335484



Photo # 6835 Location



Photo # 6836 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 16 Pad

Location ID: 335484



Photo # 6837 Location



Photo # 3178 From Inspection 708900159 conducted on 03/24/2023 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 16 Pad

Location ID: 335484



Photo # 6841 Meter calibration info not conspicuously posted