

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 242-21 Pad

Location ID: 335101



Photo # 6859 From entrance to location



Photo # 6860 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 242-21 Pad

Location ID: 335101



Photo # 5367 From Inspection 708900288 conducted on 04/13/2023 Stained soils & gravel



Photo # 6864 Stained soils & gravel