

FORM
6A
Rev
08/22

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403393565

Date Received:
05/04/2023

Rule 434.d. Out of Service Designation and Plugging List. An Operator will designate a Well as Out of Service on a Form 6A, Out of Service Designation, and the Out of Service Well is then placed on the Operator's Plugging List.

OPERATOR & CONTACT INFORMATION

OGCC Operator Number: 10560	Contact Name and Telephone:
Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME ENERGYCO	Name: Mike Hahn
Address: PO BOX 2326	Phone: (361) 200-8950
City: VICTORIA State: TX Zip: 77902	Email: mhahn@xecusa.com

WELL PLUGGING DATA

The number of Wells the Operator has plugged in the previous 12 months: 1

EVIDENCE OF FINANCIAL CAPABILITY

Provide evidence that the Operator is financially capable of meeting the timelines required by Rule 434.d.(4) for its Plugging List. (If this space is inadequate, provide as an attachment.)

We can and have in the past plugging all wells when it came time to plug. We are planning to start plugging these wells in the future.

OUT OF SERVICE DESIGNATION

Summary of Wells to be Designated as Out of Service and placed on the Operator's Plugging List

Within 2000' of a School Facility 0	Within 2000' of a Residential Building Unit within a Disproportionately Impacted Community 0
Within 2000' of a Child Care Center 0	
Within 2000' of a High Occupancy Building Unit 0	Within High Priority Habitat 0
TOTAL NUMBER OF WELLS 4	Detected Leak on Operator's CDPHE/AQCC Reg 7 Delayed Repair List 0
Valid 4 Invalid 0	

Form Submit Date: 05/04/2023

Plugging Due Date For Wells: 12/31/2027

#	Inv	API	Well Name & Number	Date Ceased Production or Utilization	Within 2000' of a School Facility?	Within 2000' of a Child Care Center?	Within 2000' of a High Occupancy Building Unit?	Within 2000' of a Residential Building Unit within a Disproportionately Impacted Community?	Within High Priority Habitat?	Detected Leak on Operator's CDPHE/AQCC Reg 7 Delayed Repair List?
1		009-05161	SCHWEITZER-NEWMAN UNIT 1	12/01/2019	No	No	No	No	No	No
2		009-06569	ALLEY 2-17	07/01/2022	No	No	No	No	No	No
3		009-06590	GAS FARM 1-17	07/01/2022	No	No	No	No	No	No
4		009-06309	MCKINLEY 1-20-WD	08/15/2022	No	No	No	No	No	No

OPERATOR COMMENT AND SUBMITTAL

I hereby certify all statements made on this form are, to the best of my knowledge at the time of submittal, true, correct, and complete.

--

Print Name: Mike HahnEmail: mhahn@xecusa.comTitle: V.P. OperationsDate: 05/04/2023**Attachment Check List****Att Doc Num****Name**

403393628

EDD-DESIGNATION

Total Attach: 1 Files