



## Decommission Input

Site Name: **ANDERSON-COOMBS1,2**

Site Type <b>PRODUCTION FACILITY</b>	Current Status <b>ABANDONED</b>	Sub Status	Active Site? <b>No</b>	Report Center <b>415860954</b>
Well Count <b>2</b>	Production Route <b>A2-06</b>	Latitude (°)	Longitude (°)	
Access Directions				

### Jobs

Job <b>ARO</b>	Job Type <b>COGCC INSPECTION</b>	Major Contractor <b>H-2 ENTERPRISES LLC</b>	Job Start Date <b>2/9/2023</b>	Job End Date <b>3/30/2023</b>
Primary Status <b>COMPLETE</b>	<p>Objective <b>ANDERSON-COMBS #1 Battery</b> Insp Doc #: 697504342 Loc ID: 322565 Comments: Well location- dog park and within a land use change- mobile home park. Tank battery- The previous inspection was conducted four year prior and perennial vegetation has failed to establish. The majority of the location is annual tumbleweeds. The adjacent reference area has the establishment of perennial grasses with annual tumbleweeds. Refer to the attached inspection photos. COGCC CAs: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.</p>			

#### Summary

On March 30, 2023, H2 mobilized to location. The site was deep ripped to a depth of 18-inches, vibrashanked and disced to prep seedbed, then drilled in Dryland Grass seed mix with QuickGuard, one bale of certified weed free straw was blown across site and crimped into dirt. The site measured 0.5 acres.

### Job Contacts

Name <b>Newby, Abbey [ERM] &lt;abbeynewby@chevron.com&gt;</b>	Title <b>RBU OE-HES</b>	Mobile Phone <b>720.833.8814</b>
--	----------------------------	-------------------------------------

### Activity Reports

Activity Start Date <b>2/9/2023</b>	Activity End Date <b>2/9/2023</b>	Onsite Rep	Activity Site Status <b>On Hold</b>	Incident?
--	--------------------------------------	------------	--	-----------

#### Summary

Collected soil samples to get lab analyticals on to determine reclamation plan

Next Planned Activity

### Daily Field Costs

Carry forward?	Cost Description	Task	Line Item	Vendor	Ticket #	Note	Amount (Cost)
Activity Start Date <b>3/30/2023</b>	Activity End Date <b>3/30/2023</b>	Onsite Rep	Activity Site Status <b>Completed</b>	Incident?			

#### Summary

Rip to 18". Vobrasjaml amd dosc area. Drill in dryland grass seed mix with QuickGuard. BGlowl and crimp 1 bale of certified weed free straw onto site. 0.5 acres

Next Planned Activity

### Daily Field Costs

Carry forward?	Cost Description	Task	Line Item	Vendor	Ticket #	Note	Amount (Cost)
<b>Yes</b>	<b>Seeding</b>	<b>247038</b>				<b>HUWA/H2 Enterprises, invoice approved by Erica Zuniga</b>	<b>5,000.00</b>

### Field Cost Summary

Cost Description <b>Seeding</b>	Task <b>247038</b>	Line Item	Vendor	Sum of Amount (Cost) <b>5,000.00</b>
<b>Total (Sum)</b>				<b>Sum of Amount (Cost) 5,000.00</b>