



Decommission Input

Site Name: **ANDERSON-COOMBS4,5**

Site Type PRODUCTION FACILITY	Current Status ABANDONED	Sub Status	Active Site? No	Report Center 415860887
Well Count 2	Production Route Watt - A2-07 T CARDENAS	Latitude (°)		Longitude (°)
Access Directions				

Jobs

Job ARO	Job Type COGCC INSPECTION	Major Contractor H-2 ENTERPRISES LLC	Job Start Date 2/3/2023	Job End Date 3/30/2023
Primary Status COMPLETE	<p>Objective ANDERSON-COOMBS 4,5 Battery Insp Doc #: 697504340 Loc ID: 323313</p> <p>Comments: Well location- meets vegetation requirements and within a land use change- mobile home park. Tank battery- The previous inspection was conducted four year prior and perennial vegetation has failed to establish. The majority of the location is annual tumbleweeds. The adjacent reference area has the establishment of perennial grasses with annual tumbleweeds. Refer to the attached inspection photos.</p> <p>CA: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.</p>			

Summary
On March 30, 2023, H2 mobilized to location. The site was deep ripped to a depth of 18-inches, vibrashanked and disced to prep seedbed, then drilled in Dryland Grass seed mix with QuickGuard, one bale of certified weed free straw was blown across site and crimped into dirt. The site measured 0.5 acres.

Job Contacts

Name Newby, Abbey [ERM] <abbeynewby@chevron.com>	Title RBU OE-HES	Mobile Phone 720.833.8814
--	----------------------------	-------------------------------------

Activity Reports

Activity Start Date 2/3/2023	Activity End Date 2/3/2023	Onsite Rep	Activity Site Status On Hold	Incident?
Summary Collected soil samples for reclaim plan.				
Next Planned Activity				

Daily Field Costs

Carry forward?	Cost Description	Task	Line Item	Vendor	Ticket #	Note	Amount (Cost)
Activity Start Date 3/30/2023	Activity End Date 3/30/2023	Onsite Rep				Activity Site Status Completed	Incident?
Summary Rip to 18". Vibrashank and disc area. Drill in DRyland Grass seed mix with QuickGuard. Crimp and blow 1 bale of certified weed free straw. 0.5 acres							
Next Planned Activity							

Daily Field Costs

Carry forward? Yes	Cost Description Seeding	Task 247038	Line Item	Vendor	Ticket #	Note HUWA/H2 Enterprises, invoice approved by Erica Zuniga	Amount (Cost) 5,000.00
------------------------------	------------------------------------	-----------------------	-----------	--------	----------	--	----------------------------------

Field Cost Summary

Cost Description Seeding	Task 247038	Line Item	Vendor	Sum of Amount (Cost) 5,000.00
Total (Sum)				5,000.00