

Inspection Photos

Location Name: SHABLE USX/AB11-11P

Location #: 417954



Photo #1

Shable USX AB11-11P (123-31799) Wellsite

Shut-In | SI



Photo #2

Shable USX AB 11-12P*, 11-11P, 11-14P Tank Battery

Battery site

Inactive | Shut-down

Equipment documented Fac. ID 481928