

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



May 2, 2023 at 10:28:09 AM  
CO



May 2, 2023 at 10:28:42 AM  
CO

Photo # 6732 From entrance to location

Photo # 6733 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 95-21 Pad

Location ID: 324053



**Photo # 6735 Stockpiled soils/insufficient BMP's,  
Soils/sediment choking off vegetation**



**Photo # 6736 Stockpiled soils/insufficient BMP's,  
Soils/sediment choking off vegetation**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources