

Inspection Photos

API: 009-06158

Operator: SOVEREIGN OPERATING COMPANY LLC

Inspection Date: 5/3/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 5/3/2023

Inspection Photos



Photo 1. Facing west toward the location. There are areas that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 5/3/2023

Inspection Photos



Photo 2. Facing northwest at the location. There are areas that are bare of vegetation. Soils may be impacted preventing vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 5/3/2023

Inspection Photos



Photo 3. Facing northeast at the south side of the location.



Inspection Photos



Photo 4. Facing south toward the undisturbed reference area which has uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 5/3/2023