

Inspection Photos

API: 009-06600

Operator: SOVEREIGN OPERATING COMPANY LLC

Inspection Date: 5/3/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 5/3/2023

Inspection Photos



Photo 1. Facing west toward the location. There are areas that are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 5/3/2023

Inspection Photos



Photo 2. Facing south at the location. There are areas that are bare of vegetation. Soils may be impacted preventing vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 5/3/2023

Inspection Photos



Photo 3. Facing northwest at the location.



Inspection Photos



Photo 4. Facing south toward the undisturbed reference area which has uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 5/3/2023